

Tools MC4

Stripping pliers

With length stop for conductor cross sections 4 mm², 6 mm² and 10 mm². Specially adapted for the FLEX-SOL-XL PV cable, for stripping small cable quantities on the site. An additional insert can be ordered for conductor cross sections of 1,5 mm², 2,5 mm², 4 mm² and 6 mm².



Cable cross section mm ²	Order-No.	See assembly instructions
4/6/10	32.6027-410	Assembly instructions MA231, MA232 www.multi-contact.com

Accessories

1 Insert for cable cross section 1,5/2,5/4/6 mm ²	32.6057-156	2 Insert for cable cross section 4/6/10 mm ²	32.6057-410
---------------------------------------------------------------------	-------------	----------------------------------------------------------------	-------------

Crimping pliers MC4¹⁾

Crimping pliers incl. locator and insert.



→ Our **Solarline** catalog contains our entire range of crimping pliers

Cable cross section mm ²	Order-No.	suitable for	See assembly instructions
2,5/4/6	32.6020-19100	MC4	Assembly instructions MA251 www.multi-contact.com
4/10	32.6020-20100	MC4	
2,5/4/6	32.6020-41100	MC4-EVO 2	

Accessories for crimping pliers MC4

1 Insert 1,5/2,5/4 mm ²	32.6021-18100
2 Insert 2,5/4/6 mm ²	32.6021-19100

Accessories for crimping pliers MC4-EVO 2

3 Insert 4/10 mm ²	32.6021-20100	Insert 4/10 mm ²	32.6021-42100
4 Locator	32.6040	Locator	32.6056

Tool case MC4

Tool case contains:

- 1** Crimping pliers MC4 (32.6020-19100)
- 2** Open end spanner set MC4
- 3** Plastic box

Optional:

- 4** Stripping pliers (Ref. 32.6027-410)
- 5** Socket wrench insert to tighten (Ref. 32.6006)
- 6** Socket wrench insert to secure (Ref. 32.6026)
- 7** Insert 4 mm²/10 mm² (Ref. 32.6021-20100)



Description	Order-No.	Tool case dimensions (mm)		
		width	depth	height
Tool case MC4	32.6019	345	275	90